

**ALTERNATIVE FUELS SAFETY
INSPECTION REPORT**

Acronym: <i>OMA</i>		County: <i>Throckmorton</i>	
PAGE 1 of 1	GPS: N <i>33.174078</i>	W <i>99.180227</i>	<input type="checkbox"/> LPG <input type="checkbox"/> CNG <input type="checkbox"/> LNG
Site ID: <i>062122</i>	Site Name: <i>Throckmorton Water Treatment</i>		
Mailing Address: <i>116 North Minter Ave Throckmorton Tx</i>			Zip:
Geographical Location: <i>200 Elm St Throckmorton Tx</i>			Zip:

Noncompliant Compliant Number of Forklifts Inspected:

*Please note that any citation(s) marked **Notify Supplier**, must be corrected by your LPG/CNG/LNG supplier or another person licensed or registered with the Railroad Commission of Texas to perform applicable installation or repair activities.

NFPA 54
CFR 49
NFPA 58
RRC RULES

**SAFETY
RULE
REFERENCE**

Notify Supplier*

Note: no violations found.

*Industrial Mfg
17933
200 psig
250 gal
1463*

Scott H. Butts

Inspector: <i>[Signature]</i>	Inspector Phone: <i>512-971-2952</i>	Date Inspected: <i>6/14/17</i>
Discussed With/Permission Granted By (X): <i>[Signature]</i>		Contact Ph No: <i>940-849-4411</i>
Printed Name: <i>Jimmy Collins</i>	Form 4 #:	Driver:
E-Mail:	RAILROAD COMMISSION OF TEXAS ALTERNATIVE FUELS SAFETY PO BOX 12967 AUSTIN, TEXAS 78711-2967 (512) 463-6462	VIN #: